

Oct 26th 1847

ran the following line for Charlotte Shell in Section 28
 T10 R 2 west Began at the $\frac{1}{2}$ mile North of said Section
 then S 60° E 322 poles 12 links to $\frac{1}{2}$ mile South witness
 standing then N 85° E 161 poles 21 links to S E Cor then
 + N 6° W 319 poles & links to the N E Cor then N 85° W 162
 poles & links to the Beginning
 James L Shell James McLawrence &
 George J Howell chain Bearers Sworn

Henry Tanner M C S

Oct 27th 1847

ran the following lines for Gideon Walker in Sec 21 & 22
 T10 R 2 west Began at a stone at the center of Sec 22
 then S 85° W 162 poles & links to $\frac{1}{2}$ mile stake west of 22
 + then S 85° W 162 poles to center of Sec 21 then N 6° W to $\frac{1}{2}$
 mile North of Sec 21
 John Swafford James L Shell
 chain Bearers Sworn

Henry Tanner M C S

Oct 28th 1847

ran the following lines in Sec 16. T10 R 2 west for John
 Swafford & others Began at the $\frac{1}{2}$ mile post then S 86° W
 325 poles 23 links to west $\frac{1}{2}$ mile post then Began at
 + South $\frac{1}{2}$ mile stake N 6° W to center of Section witness
 trees at $\frac{5}{8}$ mile not standing
 John Swafford & Doc Walker
 chain Bearers Sworn

Henry Tanner M C S

Nov 10th 1847

ran the following line in Sec 20 T9 R 2 west for Lem
 Sexton John Swafford Began at the West $\frac{1}{2}$ mile post
 + then N 85° E 327 poles 15 links from S $\frac{1}{2}$ mile post to
 North $\frac{1}{2}$ mile post N 6° W 326 poles 27 links
 Lemuel Sexton & Mr Greenwood
 chain Bearers Sworn

Henry Tanner M C S